UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. : 7,369,098 B2 APPLICATION NO. : 10/598408

: 10/598408 : May 6, 2008

DATED INVENTOR(S)

: Zhining Chen

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

On the front page of the patent, in the Foreign Application Priority Data (30), the foreign priority application number should include "-9" and appears as follows:

(30) Foreign Application Priority Data
Jan. 26, 2004 (SG)200400539-3

At the end of column 6, line 56, after claim 13, insert the following claims:

- 14. The method as in claim 13, comprising the step of providing each of the first and second array elements as a plate array element.
- 15. The method as in claim 14, comprising the step of providing each of the first and second ground conductors as a ground patch.
- 16. The method as in claim 15, comprising the step of providing the first ground patch as continuous with the second ground patch.

Signed and Sealed this

Page 1 of 1

Fifth Day of August, 2008

JON W. DUDAS Director of the United States Patent and Trademark Office